



## Description

Cleaning agent for concrete wastes, cement, mortar and rust. Clean with plenty of water 5 minutes later of application. Toxic product: rubber gloves, protection glasses and mask must be used. Avoid the contact with skin.

## Application

For cleaning floors, faced brick walls, timber formwork, spot cleaning of rust on stone, cement and lime wastes etc. For the application is required to do a previous test that verifies the suitability of the product.

## Surface preparation

The supports must be free of dust and loose particles and a test for suitability must be done before applying.

## Modes of application

Shake the product in order to homogenize it properly before applying.

- The application must be done by brush or roller.

Wet the wastes, spots, rust, etc and let act for 5 minutes at least.

Then clean the surface up with water in order to remove the wetted COAIS.

Apply without dilution or dilute in water in proportion 1:5.

In small pieces we recommend to clean by immersion.

It is recommended to do a previous test 5 days later. Verify the result in order to check if there are no colour and brightness changes.

Dry properly the tools made of metal that had contact with COAIS SUPER in order to avoid its oxidation.

## Clean up

With plenty of water.

## Data sheet

SolubilitySoluble in water

Colour/sPink

Density1,025 Kg/L ± 0,05

Acid index525 ± 15

OdourCharacteristic

## Performance

From 10 to 15 sqm per litre.

## Storage

3 years in their original packages, tightly closed and stored in cool and dry place.

## Security



## Indications of danger:

H290: May be corrosive to metals.

H314: Causes severe skin burns and eye damage.

H318: Causes serious eye damage.

## **Prudence advice:**

P234: Keep only in original container.

P264: Wash thoroughly after handling.

P280: Wear protective gloves/protective clothing/eye protection/face protection.

P301+P330+P331: IF SWALLOWED: rinse mouth. Do NOT induce vomiting.

P303+P361+P353: IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower.

P304+P340: IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing.

P305+P351+P338: IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.

P310: Immediately call a POISON CENTER or doctor/physician.