



## Description

## Application

### Modes of application

## Data sheet

Density

Dry upon touching

Colour/s

Dry for repainting

## Storage

# Security



## Indications of danger:

H317: May cause an allergic skin reaction.

## Prudence advice:

P261: Avoid breathing dust/fume/gas/mist/vapours/spray.

P272: Contaminated work clothing should not be allowed out of the workplace.

P280: Wear protective gloves/protective clothing/eye protection/face protection.

P302+P352: IF ON SKIN: Wash with plenty of soap and water.

P333+P313: If skin irritation or rash occurs: Get medical advice/attention.

P501: Dispose of contents/container in accordance with local/regional/national/international regulation